6/39

FOURTEENTH TROOP CARRIER SQUADRON Office of the Squadron Commender

AFO 133, U S Axmy 28 June 1944.

SUBJECT: Supplemental Missing Air Crew Report.

commanding General, Ninth Air Force, APO 696, U S Army., Attention: Statistical control Unit. (Thru Channels).

1. In compliance with Memorandum 35-6, your Headquarters, dated 20 May 1944, the following information is submitted to supplement Missing Air Crew Report, this headquarters, dated 7 June 1944.

a. 1st It William R. Hitztaler 0 524 956 (Pilot) and 2d Lt John H. Hendry 0 698 627 (Navigator), of aircraft C 47a No. 42-23638, have returned to this organization on 21 and 22 of June 1944 respectively.

b. Aircraft succeeded in getting over the DZ and dropping all Faratroopers, encountering much flak and anti-aircraft fire proceeding to and over the DZ.

c. All control cables were shot out of aircraft a nd Lt Hitztaler informed other crew members to bail out. Lt Hitztaler, after seeing that all members of the crew had abandoned the aircraft, bailed out.

d. The aircraft was approximately 49° 29' N., 1° 37' W at this time.

1 Incl:

Incl 1 - Overlay Map.

LEWIS S. FREDERICK; JR., M. Major, Air Corns.
Commanding.

COMPTUENTIAL